

Date of Recall submission: **03-Feb-25**

Vehicles Affected:

Make	Model	Model Year
New Flyer	XDE60	2023
New Flyer	XD40	2024
New Flyer	XD60	2024

Internal Reference Number: **N/A**

Transport Canada Recall No.: **2025-045**

Defect or Noncompliance Description: As reported by Cummins in US recall 25E004, this recall covers certain Cummins L9 engines equipped with a remote Stage 2 fuel filter (Option Number FF90943), which includes two pressurized fuel hoses (PN 6316757). This recall consists of engines potentially equipped with fuel hoses from batch code 518220. The subject engines were sold to New Flyer for installation in Transit Buses.

Safety Risk / Result: As reported by Cummins in US recall 25E004, a fuel hose that becomes disconnected will result in an engine stall, increasing the risk of a crash. A fuel leak in the presence of an ignition source may increase the risk of a fire

Remedy Description: As reported by Cummins in US recall 25E004, the remedy is to replace the subject fuel hoses with hoses having improved connector crimps.

Precautions prior to remedy, if any: As reported by Cummins in US recall 25E004, persons operating in or around the vehicle may see smoke or other visible signs of a fuel leak or smell diesel fuel.

If the above is noticed, the engine should be shut off and the local Cummins dealer/distributor called for guidance.

Remedy Material Availability: As reported by Cummins in US recall 25E004, the remedy is to replace the subject fuel hoses with hoses having improved connector crimps.

This remedy is currently available

Costs: The remedy for this recall will be performed free of charge to current owners, or for customers that perform the remedy, will be reimbursed via our normal Warranty system process.

Questions: If you have any questions about a **specific vehicle, a recall number, or to report a safety concern**, please send the request to:
safetyrecalls@nfigroup.com
In the subject line, please indicate, as applicable:
-"RECALL INFORMATION - VIN 12345678X87654321", with the Transport Canada recall number YYYY-123 (in the yellow highlighted cell on this page), OR
-"VEHICLE INFORMATION - VIN 12345678X87654321" OR
-"SAFETY QUESTION/ISSUE - VIN 12345678X87654321", OR
-"ADDRESS CHANGE - VIN 12345678X87654321"

If known, please provide the SR and fleet number of the specific vehicle, and any pertinent information to assist in getting a response to you.

Website document last updated: **25-Nov-25**